FINISHING LEVEL

	DESCRIPTION	LEAD- TIME	SLA	* SLS	© DMLS	⊗ FDM	OPOLYJET
STRIP AND SHIP	All supports/ powder removed and sandblast. Shortest lead-time and most economical	1-3 days	~	~		~	~
BASIC	STRIP & SHIP + sanding of all supports marks. Excellent for Fit and Function testing.	1-3 days	~		~		
PREMIUM	BASIC + sanding of all build lines (sandpaper grit 280) Ideal when smooth surfaces needed	2-3 days	~	*			~
MASTER	Best possible sanding. Silky smooth finish (sandpaper grit 400 + superfine soft pad) Typically used when making master models for casting	2-5 days	~				~
PAINT READY	PREMIUM sanding + primer + MASTER sanding on primer To be selected if you are to apply painting by yourself	2-5 days	~	~			~
SHOWROOM	PAINT READY + Automotive grade painting Optimal for commercial models (see more painting options in table below)	2-5 days	~	~			~
CLEAR	PREMIUM sanding + Clear coating When transparency (polycarbonate type) is needed Note: more options are available for transparency, see detailed section below)	2-5 days	*				

^{*} Coat of primer needed ** Only possible for Somos WaterShed XC 11122 resin